

Flame Temperature Sensor - Cable Break - E0100.02



The E0100.02 alarm appears on Rika pellet stoves when the connection to the flame temperature sensor is interrupted.

The unit can no longer operate. A technician must be called to service the unit.