

Oven Temperature Sensor Short Circuit - E0100.08



The E0100.08 alarm related to the oven temperature sensor appears on Rika stoves equipped with a cooking mode when a short circuit is detected in this sensor.

Cooking mode is no longer available. Contact your customer service representative. Depending on the model, the pellet heating system may still be usable.