


Diagonal Motor Failure - E0400.04



The E0400.04 alarm appears on Rika pellet stoves when a failure in the diagonal motor is detected.

Solution

1. Acknowledge the error message

If the error reoccurs, a technician must be called.