

Limiter / Overheated stove - E00020000.10 / E00020000.08



The E00020000.10 / E00020000.08 alarm appears on Rika pellet stoves when there is excessive heat buildup inside the unit due to insufficient convection.

Solution

1. Let the stove cool down
2. Disconnect the power supply
3. Check that all convection and air vents are unobstructed

Depending on the model:

1. Check the operation of the convection blower in control mode
2. In the menu, SETTINGS -> MULTIAIR FAN, set the fan speed and power to AUTO
3. Unlock/press the safety thermostat button on the back of the stove